## Appendix 2

Airbus's examples of the inspection and modification (including design change) for PDA prevention

| Model | Title   |
|-------|---|
| A320  | DOORS - CARGO COMPT DOOR HYD SYSTEM - IMPROVE LOCKING AND |
|       | INTERFACE TOLERANCE OF MANUAL SELECTOR VALVE (MSV) LEVER  |
|       | (SB A320-52-1160)   |





Fig. 2-1

| Model | Title  |
|-------|--|
| A320  | NACELLE & PYLON – AFT MOVABLE FAIRING – RIB 5 RE-DESINGN |
|       | (SB A320-54-1028)  |






Fig. 2-2

| Model | Title  |
|-------|--|
| A320  | STABILIZERS - RUDDER SIDE SHELL SANDWICH REPAIR INSPECTION |
|       | (SB A320-55-1041)  |




Fig. 2-3

| Model | Title  |
|-------|--|
| A320  | POWER PLANT - FAN COWL DOORS - INTRODUCE AN IMPROVED OIL |
|       | FILLER DOOR LATCH DESIGN ON IAE ENGINE (SB A320-71-1061) |




Fig. 2-4

| Model | Title  |
|-------|--|
| A320  | APPLY SHL TECHNOLOGY ON LANDING LIGHTS (TFU33.42.00.004) |




Fig. 2-5

Light with a reinforced lens and

cracking

without airtightness to prevent lens

Light that is airtight because an incombustible gas is sealed in the

light sough portion

| Model | Title   |
|-------|---|
| A330  | FUSELAGE - REAR FUSELAGE - RELOCATE VHF 2 ANTENNA |
|       | (SB A330-53-3112)                                 |




Fig. 2-6

| Model | Title   |
|-------|---|
| A330  | DOORS – SERVICE DOORS – IMPROVE SERVICE PANEL ACCESS DOORS IN |
|       | SECTION 16 AND 18 (SB A330-52-3108)                           |




Fig. 2-7

| Model | Title   |
|-------|---|
| A330  | DOORS - SERVICE DOORS-MODIFICATION OF LATCHING MECHANISM OF |
|       | POTABLE WATER SERVICE PANEL (SB A330-52-3086)               |




Fig. 2-8